



FABRICATORS GUIDE MARKS REMOVER

FABRICATORS GUIDE MARKS REMOVER can be used to remove guide marks on many different non-porous surfaces including pre-finished metal & powder coated products

FABRICATORS GUIDE MARKS REMOVER specialises in removing these marks from these surfaces:

- Pre-finished Metal
- Delicate Surfaces
- Mild steel & stainless steel
- Chosen by commercial welding specialists



Note: FABRICATORS GUIDE MARKS REMOVER is NOT recommended for rubber and plastic surfaces. FABRICATORS GUIDE MARKS REMOVER may also be too harsh and printers ink could dissolve.

SAFETY INSTRUCTIONS

When starting a removal job always wear safety protection before handling any of the FABRICATORS GUIDE MARKS REMOVER product. Safety goggles & chemical resistant gloves are required before using FABRICATORS GUIDE MARKS REMOVER. Wearing long sleeves & long pants are recommended to protect the skin. Always have access to water when working with FABRICATORS GUIDE MARKS REMOVER. If FABRICATORS GUIDE MARKS REMOVER does get on your skin, wash the skin with water to remove the product.

Before using FABRICATORS GUIDE MARKS REMOVER check the surface to see how clean it is. The surface does not have to be perfectly clean to start, but if the surface has substantial dirt on it, the dirt may impede the penetration process & should be washed off before removing the guide marks.

Note: Always test product on a small hidden area prior to full application.

Smart Graffiti Ireland. Apple View, Trim Road, Kildalkey, Co. Meath, C15 W702, Ireland
Tel: Ireland +353 (0)86 8111187
Email: sales@smartgraffiti.eu
www.smartgraffiti.eu

Exterior and Interior Marks Removal Process: Equipment Needed for Removal of Guide Marks:

1. FABRICATORS GUIDE MARKS REMOVER
2. Safety equipment (goggles, chemical resistant gloves, etc.)
3. Bucket of water
4. White towels

Application Method:

1. Put your chemical resistant gloves and goggles on
2. Wash down the surface with water using a rag
3. Dab the product liberally on the guide marks
4. Let the product activate on the surface for 60 seconds
5. Agitate surface with wipe
6. Wash off with water using a new rag
7. Repeat steps if mark is still showing

At the end of the job, wash down all safety equipment and tools used in the removal process to get all of the FABRICATORS GUIDE MARKS REMOVER off for reuse on the next job.

Results and Benefits:

The main differences between FABRICATORS GUIDE MARKS REMOVER & other removal methods include: dramatically reducing the time it takes to remove the marks, one application's effectiveness in removing 99% of the typical marks & no damage to the original underlying surface! FABRICATORS GUIDE MARKS REMOVER gets all of the marks off the surface within minutes while other products can take multiple applications & hours of time. FABRICATORS GUIDE MARKS REMOVER enables removal in minutes on all the typical metal surfaces which saves our customers significant time and labour.

FABRICATORS GUIDE MARKS REMOVER is most effective when used in a "wet surface" removal process. By "wet surface process" we are referring to the practice of starting with a water wetted surface and keeping the work surface wet at all times as FABRICATORS GUIDE MARKS REMOVER is applied, loosens the marks and then power washed off.

Coverage:

Varies dependent upon type of surface material 0.2 -0.5 litre/m²

With Wipes the coverage can be 0.1 -0.3 litre/m²

Smart Graffiti Ireland. Apple View, Trim Road, Kildalkey, Co. Meath, C15 W702, Ireland Tel:
Ireland +353 (0)86 8111187
Email: sales@smartgraffiti.eu
www.smartgraffiti.eu